


Using the Free CncSimulator (Lathe)


By Bob Adams

<http://www.cad2gcode.com/lathe>



From <http://www.cncsimulator.com/>



Select Screen Turning




Select Detail Settings




Enter the Data for Inch or Metric


Click on Edit Tools to select the tool #



Open the Gcode File




Adjust the % of Simulation




Start Simulation Line by Line Stop

This is the Gcode Run Screen



This is another Example



That's it!